

## DETAILS OF INSPECTION VIOLATIONS

NO.	LOCATION	REF.	POINTS	CRITICAL	DESCRIPTION
1	TOP SIDE RESTAURANT-PANTRY # 5	37	1	No	EXCESSIVE CONDENSATION BUILDUP WAS NOTED ON THE DECKHEAD OVER THE WAREWASHER AND ON THE VENTILATION VENT.
Has been forwarded to the company's Technical department in Oslo for solving.					
2	TOP SIDE RESTAURANT-HOT GALLEY	37	1	No	THE AREA WAS EXCESSIVELY HOT AND HUMID. THE EMPLOYEE WORKING IN THE SPACE WAS PERSPIRING PROFUSELY. THIS ITEM WAS CITED ON THE LAST INSPECTION.
Has been forwarded to the company's Technical department in Oslo for solving.					
3	TOP SIDE RESTAURANT	33	1	No	THE JUNCTURE WHERE THE DECK JOINS THE BULKHEAD IN THE HOT AND COLD PANTRY SECTIONS WAS EITHER NOT COVERED OR SMALL SECTIONS WHERE COVERED WITH A SOFT SEALANT. THE FRONT COUNTER AND DECK JUNCTURE WAS NOT COVERED ON THE PASSENGER SIDE OF THESE SERVICE SECTIONS EITHER.
A new sealant will be installed as soon we have a clean deck, allowing good holding ground.					
4	TOP SIDE RESTAURANT -COLD SIDE BUFFET	*	0	No	IT IS RECOMMENDED THAT CRUSHED ICE BE USED FOR THE DISPLAY OF FOOD ITEMS ON THE COLD BUFFET LINE TO ENSURE THAT THE FOOD CONTAINERS CAN BE EASILY SUBMERGED INTO THE ICE TO MAINTAIN PROPER COOLING FOR THE FOOD ITEMS.
Has been forwarded to the company's Technical department in Oslo for solving					
5	GALLEY-POTWASH	26	0	Yes	A COUPLE OF SOILED POTS WERE STORED AS CLEAN.
Training given to the potwasher and constant survey implemented.					
6	FOOD SERVICE GENERAL	20	2	No	SEVERAL CUTTING BOARDS WERE FOUND SCRATCHED AND PITTED. IT WAS NOTED THAT SOME BOARDS ARE BEING SANDED BUT STILL DID NOT HAVE A SMOOTH SURFACE FOR EASY CLEANING.
The cutting boards were replaced with new ones. The ones pointed out have been planed to a smooth, easy cleanable surface.					
7	TOY OF YACHT-BAR PANTRY	21	0	No	THE ICE MACHINE DOOR WAS NOT FUNCTIONING PROPERLY MAKING OPENING THE DOOR VERY DIFFICULT.
Has been maintained					
8	POTABLE WATER	08	0	No	THERE WAS NO REDUCED PRESSURE BACKFLOW ASSEMBLY INSTALLED ON EITHER OF THE INTERNATIONAL SHORE
Wrong type delivered in October. New on order.					
9	POTABLE WATER	06	0	No	

THE HALOGEN ANALYZER-CHART RECORDER CHARTS DID NOT HAVE A RANGE OF 0.0 TO 5.0 PPM. THE CHARTS BEING USED HAD A RANGE OF 0.0 TO 100 PPM.

Appropriate charts have been ordered.

10 **CORRECTIVE ACTION STATEMENT**

\*

0

No

IN DEVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION, CRITICAL-ITEM DEFICIENCIES (DESIGNATED WITH YES IN CRITICAL COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT, SHOULD INCLUDE STANDARD OPERATING PROCEDURES AND MONITORING PROCEDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.

PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: [VSP@CDC.GOV](mailto:VSP@CDC.GOV)

USE EMAIL MESSAGE SUBJECT LINE: SHIP NAME - CAS - [INSERT INSPECTION DATE] .